




COMPONENTS MARKED AS XX ARE NOT FITTED ON THIS MODEL




VM, -2B-320X40









D3. -28-32DX40



H8. -28-32DX40




F3. -28-32DX40



[www.electronicrepair.net](http://www.electronicrepair.net)

D2.-28-32DX40



F6. -28-32DX40

